

## Optional Accessories

Lifting lever

Lifting knob



Lifting cable



- Lifting
    - Lifting lever **21EZA198** (ISO/JIS Type),  
**21EZA199** (ASME/ANSI/AGD Type)
    - Lifting knob **21EZA105** (ISO/JIS Type),  
**21EZA150** (ASME/ANSI/AGD Type)
    - Lifting cable **21JZA295**
  - SPC Cable:
    - 905338** (1 m)
    - 905409** (2 m)
  - USB Input Tool Direct (2 m): **06AFM380F**
- Note: Please separately purchase **USB-ITPAK** since there is no data output switch on the measurement instrument.
- Input Tool Series
    - IT-016U** (USB Keyboard Signal Conversion Type):  
**264-016-10**
    - IT-007R** (RS-232C Communication Conversion Type):  
**264-007**
  - Connecting Cables for **U-WAVE-T** (160 mm):  
**02AZD790F**
  - For foot switch: **02AZE140F**
  - Digimatic Mini-Processor **DP-1VA LOGGER: 264-505**
  - **ID-SS** can be used in standard work environments.
- The following is excerpted from JIS Z9110: 2010 General rules of recommended lighting levels; 5.4 Factories:

Luminance (lux)	Settings and procedures
1500	Very detailed visual work
750	Detailed visual work; design and drawing work
500	Regular visual work such as work carried out in a factory; monitoring work such as using instrument panels and control panels
300	Administrative work carried out in a warehouse
200	Control rooms, bathrooms, and places where manual light work is carried out
150	Work such as loading, unloading, and shifting loads
100	Hallways, corridors, entrances and exits, and warehouses
50	Indoor emergency staircases

## Dimensions

